

7003.1^{Q&As}

Avaya Communication Server 1000 for Avaya Aura Implementation
Exam

Pass Avaya 7003.1 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass2lead.com/7003-1.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



QUESTION 1

A customer has a Communication Server (CS) 1000E RIs. 7 x system with a System Manager as the primary Security Server that has been designated as a Deployment Server. The application file (.nai) has been uploaded to the deployment manager library. The customer has added an element to the security domain and wants to deploy software applications to the element. With respect to deployment services, which statement is false?

- A. Deployment Manager has logicto prevent applications beingdeployed on unsupported hardware platform.
- B. MAS application has its own separate .nai file.
- C. IM and Presence application has its own separate .nai file.
- D. MAS can be deployed on the same server as Session Manager.

Correct Answer: D

QUESTION 2

A customer has successfully installed a Common Processor Media Gateway (CPMG) in a Communication Server (CS) 1000E system. The MGC has registered with the Call Server.

What is displayed on the CPMG LED display to confirm successful registration?

- A. The MGC display will read "PASS"
- B. The MGC display will read "LOAD"
- C. The MGC display will read "Exxx" (E000)
- D. The MGC display will show Superloop and shelf number of MG 1000E

Correct Answer: D

QUESTION 3

A technician is upgrading an option 11C RIs. 5x to a communication server 1000E SA RIs. 7x based on a CPPM CS, COTS SS with 4 chassis media gateway (MG), 100IP sets, 124 digital sets, 30 analog sets and one PR12 DID connection for the incoming and outgoing calls cannot be made from all type of the sets except for the sets in MG3.

When the technician is finished with the upgrade it is noticed during the acceptance testing that outgoing calls cannot be made from all type of the sets except for the sets in mG3. All the sets have dial tone.

Which statement describes what is causing this issue?


- A. The PR 12 loop disabled in MG3
- B. The DB 128 is not installed in MG3
- C. The COTS Signaling Server is faulty

D. All MGs are unregistered except MG3

Correct Answer: D

QUESTION 4

Click the exhibit button During the installation the installation of a Communication Server 1000E RIs. 7x High Availability system for a customer, attempts to register an IP 1230 Desktop telephone with the system are unsuccessful. Network connectivity issues have already been ruled out, however a system configuration issue is suspected.



What is causing the problem?

- A. The virtual gateway application is not enabled.
- B. The proper firmware has not been uploaded for this telephone.

- C. The Line Terminal Proxy Server is not enabled for the node
- D. The Datagram Transport Layer Security (DTLS) Policy off.

Correct Answer: C

QUESTION 5

A customer has a Communication Server (CS) 1000 RIs. 7x Co-Resident system, and needs to access the Call Server Overlay Shell to use the Call Server Overlay commands.

Which two commands are used to access the Call Server Shell? (Choose two)

- A. cspdt
- B. cslogin
- C. csaccess
- D. csconsole

Correct Answer: BD

[7003.1 VCE Dumps](#)

[7003.1 Practice Test](#)

[7003.1 Study Guide](#)