

NS0-182^{Q&As}

NetApp Certified Storage Installation Engineer, ONTAP

Pass NetApp NS0-182 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass2lead.com/ns0-182.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by NetApp
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



QUESTION 1

At a new Installation, you run Config Advisor and see the warnings shown In the exhibit.


What should you do to correct the warnings on the node?

- A. Set the flow control on all the 10GbE ports to none, and delete the AutoSupport settings.
- B. Set the flow control on all of the 10GbE or 40GbE cluster interconnect ports to None.
- C. Delete all of the AutoSupport settings, and change the flow control to full.
- D. Set the flow control on all the 1GbE ports to match the 10GbE pods.

Correct Answer: B

QUESTION 2

Select the Exhibit tab.



You finished the installation of a new FAS8200 system. The customer wants to use FC and 10G Ethernet but only has

the onboard UTA2 ports available.

Referring to the exhibit, which two sets of ports would the customer use? (Choose two.)

- A. e0e, 0f and e0g, 0h
- B. 0e, 0f and e0g, e0h
- C. 0e, e0f and 0g, e0h
- D. e0e, e0f and 0g, 0h

Correct Answer: AD

QUESTION 3

You have just installed a new AFF A220 4-node cluster with ONTAP 9.5 for a customer. Which two cluster switches are supported in this scenario? (Choose two.)

- A. Cisco Nexus 5596UP
- B. Brocade 6510
- C. Cisco MDS 91485
- D. NetApp CN1610

Correct Answer: AD

QUESTION 4

A customer has an AFF A800 with 24 internal drives and is running out of storage capacity. In this scenario, which action will solve this issue?

- A. Insert more internal NVMe SSD drives.
- B. Attach an additional DS212C shelf, filled with drives.
- C. Attach an additional DS460C shelf, filled with drives.
- D. Insert more internal SSD drives.

Correct Answer: A

QUESTION 5

You completed the installation of an AFF A700s with NetApp CN1610 switches. You used ports e0a and e0f with breakout cables to connect the controllers to the interconnect switches. After completing the cluster setup, ports e0e and e0i are not visible in OnCommand System Manager.

In this scenario, what caused this problem?

- A. Breakout cables were used and the second port on the same ASIC became disabled.
- B. This is a hardware error and you must open a case with NetApp Support.
- C. You must first enable the ports using the network port modify command.
- D. You are missing a license to enable those ports.

Correct Answer: C

[NS0-182 VCE Dumps](#)

[NS0-182 Practice Test](#)

[NS0-182 Braindumps](#)