500-920^{Q&As}

Cisco Data Center Unified Computing Infrastructure Troubleshooting (DCITUC)

Pass Cisco 500-920 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass2lead.com/500-920.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

In a Cisco UCS Manager, if all KVM sessions to each server fail to start, what is likely causing the problem?

A. Cisco UCS Manager has a problem

B. The Fabric Interconnect to which you are connected has a problem

C. The I/O Modules in the chassis are the problem

D. The workstation you are using to connect to the KVM session is the problem

Correct Answer: D

QUESTION 2

After installing a new UCS M4 server, which two Cisco Integrated Management Controller connectivity options do you have? (Choose two)

A. XML API Access

B. Web Access

C. In-band Access

D. SNMP

E. Out-of-Band Access

Correct Answer: AC

QUESTION 3

Which ethernet port type is used when configuring UCS Fabric Interconnect connections to Cisco UCS C-series servers?

A. Server Port

B. Uplink Port

C. Direct Connect Port

D. Service Profile Port

Correct Answer: B

QUESTION 4

What three options should be verified, when you are able to connect to Cisco UCS Manager, but unable to open a KVM

session to a blade? (Choose three)

A. Verify TCP port 2068 is not blocked by an ACL or Firewall

B. Confirm the IP Address assigned to UCS Manager is the same as the KVM address

C. Verify the KVM IP Address is on the same ip subnet as the virtual machines

D. Confirm the KVM IP Address is added to the route table in Cisco UCS Manager

E. Confirm the IP Address assigned to the KVM is not a duplicate IP

F. Verify the KVM IP Address is on the same subnet as the Fabric Interconnect management address

Correct Answer: ADE

QUESTION 5

What occurs that causes a Split Brain Issue with Fabric Interconnects?

A. The subordinate Fabric Interconnect detects heartbeat failure and declares itself primary

B. Manage configuration changes made with UCS Manager

C. A quorum tie occurs that must be resolved by the SEEPROM

D. Both cluster links fail

Correct Answer: A

[500-920 PDF Dumps](https://www.pass2lead.com)   [500-920 VCE Dumps](https://www.pass2lead.com)   [500-920 Exam Questions](https://www.pass2lead.com)