75940X^{Q&As}

Avaya Converged Platform Integration

Pass Avaya 75940X Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass2lead.com/75940x.html

100% Passing Guarantee
## 100% Money Back Assurance

Following Questions and Answers are all new published by Avaya Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

Refer to the exhibit.

In the deployment shown in the exhibit, how is High Availability achieved across the two Data Centers?

A. By ensuring that the L2 VLANs are extended across to both Data Centers.

B. By managing both Data Centers using the same vCenter Server and using vMotion and DRS.

C. By using Virtualization Provisioning Service (VPS) to automate the provisioning of the network hardware and vSwitches across the two Data Centers.

D. By using Avaya Aura?Application High Availability features.

Correct Answer: C

Reference: https://downloads.avaya.com/css/P8/documents/100182353

QUESTION 2

![Pass2Lead](https://Pass2Lead.com)
Refer to the exhibit.

	A	B	C	D	E	F	G	H	I
2	Build Code	Assembled Units	From Device RMU/Port	Connects to Unit	To Switch RMU/Port				
1452	2D E3ÍS/G/GS	Gateway - 1	E5	VSP4K1	P1	1 – P1	G4501 – E5	10	Gray
1454	2D E3ÍS/G/GS	VSP 4800 – 2	P3	VSP4K1	P3	1 – P3	4k2 – P3	10	Gray
1455	2D E3ÍS/G/GS	VSP 4800 – 2	P4	VSP4K1	P4	1 – P4	4k2 – P4	10	Gray
1456	2D E3ÍS/G/GS	VSP 4800 – 2	P5	VSP4K1	P5	1 – P5	4k2 – P5	10	Gray
1457	2D E3ÍS/G/GS	VSP 4800 – 2	P6	VSP4K1	P6	1 – P6	4k2 – P6	10	Gray
1458	2D E3ÍS/G/GS	VSP 4800 – 2	P7	VSP4K1	P7	1 – P7	4k2 – P7	10	Gray
1459	2D E3ÍS/G/GS	VSP 4800 – 2	P8	VSP4K1	P8	1 – P8	4k2 – P8	10	Gray
1460	2D E3ÍS/G/GS	VSP 4800 – 2	P6	VSP4K1	P9	1 – P9	4k2 – P9	10	Gray
1461	2D E3ÍS/G/GS	VSP 4800 – 2	P10	VSP4K1	P10	1 – P10	4k2 – P10	10	Gray
1462	2D E3ÍS/G/GS	Server ACR – 1	N2	VSP4K1	P18	1 – P18	SVR01 – N2	15	Gray
1463	2D E3ÍS/G/GS	Server ACR – 2	N2	VSP4K1	P19	1 – P19	SVR02 – N2	15	Gray
1469	2D E3ÍS/G/GS	Server ACR – 1	N0	VSP4K1	P26	1 – P26	SVR01 – N0	15	Black
1470	2D E3ÍS/G/GS	Server ACR – 2	N0	VSP4K1	P27	1 – P27	SVR02 – N0	15	Black
1476	2D E3ÍS/G/GS	Server ACR – 1	IMM	VSP4K1	P35	1 – P35	SVR01 – IMM	15	Black
1482	2D E3ÍS/G/GS	EMC Storage	SPA LAN	VSP4K1	P43	1 – P43	VNX – SPA LAN	15	Black
1485	2D E3ÍS/G/GS	EMC Storage	SPA P0	VSP4K1	P50	1 – P50	VNX – SPA P0	5M	Aqua
1486	2D E3ÍS/G/GS	Gateway – 1	E6	VSP4K2	P1	2 – P1	G4501 – E6	10	Gray
1488	2D E3ÍS/G/GS	VSP 4800 – 1	P3	VSP4K2	P3	2 – P3	4k1 – P3	10	Gray
1489	2D E3ÍS/G/GS	VSP 4800 – 1	P4	VSP4K2	P4	2 – P4	4k1 – P4	10	Gray

◄ ► ... Switch Wiring | Power Cord Wiring | Serial Numbers | Software Versions | Licenses | Calc | Customer Questionnaire | Network Data

An Administrator notices that a Service Status Warning is being received by Avaya Orchestrator indicating that port 27 on VSP 4850-1 is down.

Based on the contents of the Customer and Network Lifecycle Workbook in the exhibit, which equipment is connected to this port?

A. VSP4K1, port 27

B. Server/ACR-2, Interface NO

C. Server/ACR-1, Interface NO

D. VSP4K1, Port 26

Correct Answer: A

QUESTION 3

How can the administrator check the status of all services being monitored by Avaya Orchestrator?

A. It is not possible. Services are displayed on a per-Host basis only.

B. By navigating to Quick View-All Service Problems.

C. By navigating to Details-Service Status.

D. By navigating to ACP 4200 Configuration Wizard-Service.

Correct Answer: B

Reference: https://downloads.avaya.com/css/P8/documents/101061680

QUESTION 4

Refer to the exhibit.

The CPU performance of Communication Manager (CM) shows a significant difference depending on the call rates.

Which statement about making configuration changes is true?

A. Increasing the number of Virtual CPUs allocated to CM might help to reduce this difference.

![Pass2Lead](https://Pass2Lead.com)
B. Ensuring that a secondary CM is available to allow for load-balancing might help to reduce this difference.

C. Migrating the CM Virtual Machine to another ESXi host that is less busy might help to reduce this difference.

D. Reducing this difference is not necessary because this is expected behavior.

Correct Answer: B

QUESTION 5

Refer to the exhibit.

What does the IP address 10.1.1.1 represent?

A. The IP address of the EMC storage

B. The SMLT IP address of the two VSP 7200 switches

C. The Virtual IST IP address of the two VSP 7200 switches

D. The VRRP IP address of the two VSP 7200 switches

Correct Answer: D