Pass2Lead

E20-885^{Q&As}

VNX Solutions Expert Exam for Implementation Engineers

Pass EMC E20-885 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass2lead.com/e20-885.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

![Pass2Lead logo](https://Pass2Lead.com)
QUESTION 1

A customer has an EMC VNX with the total efficiency pack. Several applications access the VNX including the company\'s Exchange 2010 email system. The Exchange log files are on a dedicated RAID 1/0 LUN and the mailbox databases are on a storage pool shared by other applications. What can be done to improve performance in the Exchange environment?

A. Enable FAST Cache on the storage pool

B. Enable FAST VP on the storage pool

C. Enable FAST Cache on the log LUN

D. Enable write-through caching

Correct Answer: A

QUESTION 2

You are investigating a performance problem on a VNX. The customer is using the array for storage for

their VMware servers, which is connected through a dual port 10G iSCSI IO module. They have divided

the available disks into two separate Storage Pools.

They are seeing 40% CPU usage on SPA and 85% CPU usage on SPB. After investigating, you find that

all LUNs in the second Storage Pool are now owned by SPB.

How should this be explained?

A. Block Deduplication is enabled for all LUNs in the second Storage Pool.

B. SPA iSCSI NIC has malfunctioned and all LUNs have trespassed.

C. Failover mode has not been set correctly.

D. SPB had a CPU malfunction and needs to be replaced.

Correct Answer: A

QUESTION 3

A customer has a production CLARiiON replicating to a secondary CLARiiON at a remote site using MirrorView/S. The customer wants to upgrade to new EMC VNX, but due to cost constraints, they can only upgrade one of the CLARiiON arrays at this time.

How do you advise the customer?

A. A mirror relationship cannot exist between CLARiiON and VNX LUNs.

![Pass2Lead](https://Pass2Lead.com)
B. Replication between faster ports and slower ports is not supported.

C. Storage pool LUNs cannot mirror to RAID group LUNs.

D. VNX can only replicate to other VNX arrays.

Correct Answer: A

QUESTION 4

A VDI environment is using VNX over iSCSI for its data stores. All planning trials with an application test harness, and thorough HA simulation, indicated a maximum of 1000 virtual desktops for the VNX pool for acceptable performance. The actual number of desktops allocated to the pool is 750.

Users have reported poor virtual desktop performance, and the VNX Administrator has observed a

consistently high level of read I/O on the VNX LUNs servicing this VDI solution.

What is a possible cause of this situation?

A. Desktops have insufficient RAM allocation.

B. A desktop virus has triggered CAVA antivirus scan for all desktops.

C. An employee shift change triggered excessive I/O to load user profiles.

D. VNX FAST Cache was not sized correctly.

Correct Answer: A

QUESTION 5

When using AVM, when is it acceptable to stripe all dvols across the same RAID Group?

A. When using Flash drives

B. When using NL-SAS drives

C. When using SAS drives

D. It is never acceptable

Correct Answer: A

Latest E20-885 Dumps   E20-885 Practice Test   E20-885 Exam Questions