HP2-T26^{Q&As}

Servicing HP BladeSystem Solutions

Pass HP HP2-T26 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass2lead.com/hp2-t26.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

🔧 **Instant Download** After Purchase

🔧 **100% Money Back** Guarantee

🔧 **365 Days** Free Update

🔧 **800,000+** Satisfied Customers

![Pass2Lead](https://Pass2Lead.com)
QUESTION 1

An HP ProCurve 6120G/XG Ethernet Blade Switch has a blinking amber LED for 10/100/1000 port 1. What does this indicate?

A. network link fault

B. link activity at 1 Gb/s

C. prefailure warning

D. switch failure

Correct Answer: B

QUESTION 2

Your customer has a business critical HP BladeSystem enclosure and wants to protect it with additional service coverage. The company\\'s requirements are 24x7 and functionality must be restored within a defined time.

Which HP Service offering is needed to fulfill the customer\\'s requirements?

A. HP Critical Advantage L3

B. HP Proactive Select 30 Credit

C. HP 6 hour Hardware Support Onsite Call-to-Repair Service

D. HP 24x7 hour Response, Hardware Support Onsite Service

Correct Answer: C

QUESTION 3

Which ProLiant Server Blade utilities are available to check the system information and BIOS version? (Select two.)

A. ROM-Based Setup Utility

B. Diagnostic Utility

C. Inspect Utility

D. Option ROM Configuration for Arrays Utility

E. Network Boot Utility

Correct Answer: AC

QUESTION 4

![Pass2Lead](https://Pass2Lead.com)
An administrator is struggling with the configuration of a c7000 enclosure and calls HP support for assistance. What is the best way to forward the inventory and event logs to HP support.

A. Capture the screen shots of the c7000 enclosure settings through OA.

B. Capture the integrated Management Log of all servers.

C. Capture the configuration scripts through the Onboard Administrator.

D. Capture the screen shots of insight Display.

Correct Answer: C

QUESTION 5

A customer purchased a c7000 blade enclosure, fully populated with blade Gen8 servers and Care Pack services. Several days later, the customer purchased an HPZR30W, an HP UPS R8000/3, and two iPDUs.

Which new items will be covered in the Care Pack services? (Select two.)

A. both iPDUs if they are mounted in a different rack from the c7000

B. the ZR30W (30 inch) monitor put on top of a rack.

C. both iPDUs if they are mounted in the smae rack as the c7000

D. the UPS R8000/3 if it is mounted in another rack

E. the UPS R8000/3 if it is in the same rack as the c7000

Correct Answer: AC

[HP2-T26 PDF Dumps](#)   [HP2-T26 Practice Test](#)   [HP2-T26 Exam Questions](#)