HP0-Y52^{Q&As}

Applying HP FlexNetwork Fundamentals

Pass HP HP0-Y52 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass2lead.com/hp0-y52.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

![Pass2Lead](https://Pass2Lead.com)
QUESTION 1

Refer to the exhibit.

```
ProVision-1# show version
Image stamp:
/ws/swbuildm/KA_rel_irvine_qaoff/code/build/tam(swbuildm_KA_rel_irvine_qaoff_re
l_irvine)
Mar 13 2013 11:26:17
KA.15.10.0011
542
Boot Image: Primary
```

What can a network administrator determine from the output in the exhibit?

A. The switch will boot the primary software on its next boot.

B. The switch has no software stored in the secondary slot.

C. The switch is using the config file in the primary slot for its startup-config.

D. The switch booted the primary software on its previous boot.

Correct Answer: D

QUESTION 2

A company wants a modular switch for the access layer at its main campus and for several branch offices. Which HP Switch Series is best suited for this role?

A. HP 11900

B. HP 12900

C. HP 5900

D. HP 5400R

Correct Answer: C

QUESTION 3

Refer to the exhibit.

![Pass2Lead](https://Pass2Lead.com)
```
Switch-C# show spanning tree
<-output omitted->
  IST Mapped VLANs      : 1-4094
  Switch MAC Address    : 0019bb-acd640
  Switch Priority       : 8192
  Max Age   : 20
  Max Hops  : 20
  Forward Delay : 15
  Topology Change Count     : 10
  Time Since Last Change    : 8 mins
  CST Root MAC Address  : 0017a4-742700
  CST Root Priority     : 4096
  CST Root Path Cost    : 20000
  CST Root Port         : Trk1
  <-output omitted->

Port  Type        Cost      Priority   State        :   Designated Bridge
----  ---------   -------   --------   -----------  +   -----------------
1     100/1000T   20000      128       Blocking     :   001635-b65040
2     100/1000T   20000      128       Forwarding   :   0019bb-acd640
3     100/1000T   20000      128       Blocking     :   0017a4-742700
4     100/1000T   20000      120       Forwarding   :   001630-4907d1
<-output omitted->
Trk1  100/1000T   20000      128       Forwarding   :   0017a4-742700
```

Based on the output in the exhibit, which statement is correct about the spanning tree protocol running in this network?

A. Switch- is a root switch.

B. Port 2 is a designated port.

C. Port 3 is a root port.

D. Port 4 is a designated port.

Correct Answer: B

QUESTION 4

Which HP solution provides network optimization and automated network provisioning to its customers?

A. Intelligent Management Center NTA

B. FlexNetwork Architecture

C. Intelligent Resilient Framework

D. Software-defined Networking

Correct Answer: D

![Pass2Lead](https://Pass2Lead.com)
QUESTION 5

A network administrator deletes old files in the flash file system of an HP Comware switch. The administrator then notices that the amount of free space available has not changed. Which command must the administrator execute to free up the space from deleted files?

A. reset recycle-bin

B. recycle-bin cleanup

C. cleanup recycle-bin

D. recycle-bin empty

Correct Answer: A

[HP0-Y52 PDF Dumps](https://www.pass2lead.com/hp0-y52.html)   [HP0-Y52 VCE Dumps](https://www.pass2lead.com/hp0-y52.html)   [HP0-Y52 Braindumps](https://www.pass2lead.com/hp0-y52.html)