HPE6-A44^{Q&As}

Scalable WLAN Design and Implementation (SWDI) 8

Pass HP HPE6-A44 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass2lead.com/hpe6-a44.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

An administrator deploys an Aruba Mobility Controller 7005 to a branch office. The administrator accidentally disables the console port on the controller. Which controller command should the administrator use to re-enable the console part?

A. mgmt-user console

B. console enable

C. console reset

D. no mgmt-user console-block

Correct Answer: D

Reference: https://community.arubanetworks.com/t5/Controller-Based-WLANs/How-to-Disable-ConsoleAccess-on-Controller-AOS-8-0/ta-p/292014

QUESTION 2

Which methods can be used to configure RAP redundancy when connected to two redundant Aruba Mobility Controllers (MCs) in the DMZ? (Select two.)

A. Virtual IP address of the two controllers.

B. Active and Standby AAC.

C. Primary and backup LMS IP addresses.

D. IPSec High Availability (HA) between two cluster members.

E. AirWave direction to RAPs redundant Mobility Controllers.

Correct Answer: BE

QUESTION 3

An administrator makes a configuration change on a Mobility Master (MM) that causes a Managed Controller to lose connectivity with the MM. The MC attempts auto roll-back, but this fails.

How should the administrator recover from this problem?

A. Access the CLI of the MC and execute the no command to revert the changes.

B. Access the CLI of the MC and identify the previous configuration file the MC should use.

C. Reboot the MC to force auto-roll back to occur.

D. Access the CLI of the MC, execute the disaster-recovery command, and undo the changes.

![Pass2Lead logo](https://Pass2Lead.com)
Correct Answer: D   3 / 3

QUESTION 4

An administrator configures AirGroup policies to define which Apple services are visible and available to wireless users in a campus WLAN. However, the policies are not being enforced. Where must the administrator enable the AirGroup functionality on the Mobility Master (MM) so that the policies will be in effect?

A. At the Mobility Master hierarchy

B. At the controller level in the Managed Network hierarchy

C. At the Access Points level in the Managed network hierarchy

D. At the global Managed Network hierarchy

Correct Answer: A

QUESTION 5

Which configuration command needs to be executed on an Aruba Mobility Controller (MC) to forward AP statistical data to an AirWave Management Platform (AMP)?

A. snmp-server

B. tunneled-node-server

C. ssh-server

D. mgmt-server

Correct Answer: D

[HPE6-A44 VCE Dumps](#)   [HPE6-A44 Practice Test](#)   [HPE6-A44 Braindumps](#)