# NS0-509^Q&As

## NetApp Certified Implementation Engineer - SAN - ONTAP

## Pass NetApp NS0-509 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

**https://www.pass2lead.com/ns0-509.html**

### 100% Passing Guarantee
### 100% Money Back Assurance

Following Questions and Answers are all new published by NetApp
Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

![Pass2Lead](https://Pass2Lead.com)
**QUESTION 1**

Exhibit.



Referring to the exhibit, which FC LIF would cause a path failure on a host connecting to a LUN?

A. fcp_sanluns01prod02p0e

B. fcp_sanluns01prod02p0g

C. fcp_sanluns01prod02p0g

D. fcp_sanluns0lptodOlp0e

Correct Answer: A


**QUESTION 2**

Exhibit.

The VMware ESX host discovers only two of four paths to a LUN on a new ONTAP cluster. Referring to the exhibit, which statement Is correct?

A. The fabric zoning configuration does not allow access to the target LIFs.

B. The igroup does not contain the. WWPN of one initiator.

C. The fabric name server is disabled.

D. The initiator HBA is not connected to the fabric.

Correct Answer: D

**QUESTION 3**

Click the Exhibit button.

| Question | Exhibit |
```
cluster01::> system hardware unified-connect show -node cluster01-01
                        Current  Current    Pending  Pending  Admin
Node             Adapter  Mode     Type       Mode     Type     Status
cluster01-01     0c       can      target     -        -        online
cluster01-01     0d       can      target     -        -        online
cluster01-01     1a       fc       target     -        -        offline
cluster01-01     1b       fc       target     -        -        offline
cluster01-01     1c       fc       initiator  -        -        online
cluster01-01     1d       fc       initiator  -        -        online
6 entries were displayed.
```

Referring to the exhibit, what happens when you change the type for port 1a from target to initiator?

A. The port type for 1a changes to initiator, and you must reboot the controller for the changes to take effect.

B. You receive an error message that you must take ports 1a and 1b offline before you can change the type.

C. B. You receive an error message that you must take the port 1a offline before you can change the type.

D. The port type for 1a and 1b changes to initiator, and you must reboot the controller for the changes to take effect.

Correct Answer: A

**QUESTION 4**

An administrator has a new AFF A220 system with two DS224C disk shelves and wants to validate if the shelf cabling is correct.

Which resource would be used to accomplish this task?

A. Config Advisor

B. OnCommand Unified Manager (OCUM)

C. OneCollect

D. Interoperability Matrix Tool (IMT)

Correct Answer: A

Reference: https://library.netapp.com/ecm/ecm_download_file/ECMLP2842667

**QUESTION 5**

A customer\\'s Red Hat Linux 7.0 server\\'s Linux native DM-MP settings for multi pa thing have not been set correctly. In this scenario, what would cause this problem?

A. The multi path, conf file contains the blacklist stanza;

B. Challenge-Handshake Authentication Protocol (CHAP) is not enabled.

C. The rdloaddriver=scsi_dh_alua was not added to the end of the boot loader file.

D. The incorrect WWID was added to the multipath.conf file.

Correct Answer: D

Latest NS0-509 Dumps          NS0-509 PDF Dumps          NS0-509 Study Guide