NS0-515^{Q&As}

NetApp Certified Implementation Engineer - SAN, E-Series

Pass NetApp NS0-515 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass2lead.com/ns0-515.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by NetApp
Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

Which two steps are required to enable multifactor authentication on an E-Series system? (Choose two.)

A. Test SSO login

B. Configure In-Band Management

C. Map roles

D. Configure LDAP

Correct Answer: AB

Reference: https://www.netapp.com/us/media/tr-4712.pdf

QUESTION 2

What is the minimum number of drives needed to create a Dynamic Disk Pool?

A. 12

B. 8

C. 3

D. 11

Correct Answer: D

Reference: https://www.netapp.com/us/media/tr-4652.pdf (5)

QUESTION 3

What are two methods for setting the host protocol configuration on the E2800 controller with a 4-port 16Gbps FC or 10Gbps iSCSI SFP+ host interface card (HIC)? (Choose two.)

A. Set at the factory, based on the order

B. Change the QSFP type in the HIC

C. Change the Feature Pack in the SANtricity System Manager

D. Set in the Hardware tab using SANtricity System Manager

Correct Answer: CD

Reference: https://docs.netapp.com/ess-11/index.jsp?topic=%2Fcom.netapp.doc.e-2800-sysmaint% 2FGUID-C2A2AAC4-A1B9-468F-8CE8-862D32917840.html

![Pass2Lead logo](https://Pass2Lead.com)
QUESTION 4

A customer has an E5760 array with a 30-drive Dynamic Disk Pool (DDP) that uses 800 GB SSD drives. The customer needs to expand the pool by one drive but has only a 1.6 TB SSD drive available.

In this scenario, what happens when the customer attempts to add the 1.6 TB drive to the existing pool?

A. The pool is expanded by 1.6 TB

B. The pool is expanded by 1.6 TiB

C. The pool is expanded by 800 GB

D. An error occurs, and the add fails

Correct Answer: A

QUESTION 5

Which iSCSI setting would you change from its default value to increase the throughput of an iSCSI host port on a NetApp E-Series system?

A. maximum transmission unit (MTU)

B. flow control

C. Challenge-Handshake Authentication Protocol (CHAP)

D. Time to Live (TTL)

Correct Answer: A

Reference: https://www.netapp.com/us/media/tr-3409.pdf

QUESTION 6

In which two locations would you find the WWPNs for a Windows host? (Choose two.)

A. FC switch

B. host\\'s BIOS

C. Windows Device Manager

D. HBA vendor\\'s utility

Correct Answer: AD

Reference: https://library.netapp.com/ecm/ecm_download_file/ECMP1532524 (7)

QUESTION 7

![Pass2Lead](https://Pass2Lead.com)
Click the Exhibit button.

Supported Adapter Cards – E2812 Duplex 16Gb 10GbE Base-T 11.50 SANtricity OS							
Adapters							
Priority	**Category**	**Bus Type**	**Mktg Part No**	**Images**	**LED**	**Mfg Part No**	**Description**
1	Block Access	PCIe2	X-56023-00-0E-C		View		HIC.E2800.10Gb Base-T.2-ports, -C
2	Block Access	PCIe2	X-56026-00-0E-C		View		HIC.E2800.12Gb SAS.2-ports, -C
3	Block Access	PCIe2	X-56027-00-0E-C		View		HIC.E2800.12Gb SAS.4-ports, -C

You ordered a NetApp E2812 Duplex 16GB 10 GbE Base-T system. Referring to the exhibit, what is the maximum number of 10GbE Base-T ports available to be used?

A. 8

B. 4

C. 6

D. 12

Correct Answer: B

QUESTION 8

A company implemented Automatic Load Balancing (ALB). When the controller workloads are monitored, it becomes obvious that there is an imbalance and that ALB is not working correctly.

In this scenario, what are two causes of the problem? (Choose two.)

A. The company implemented a load balancing min-min algorithm that does not support ALB

B. The company implemented an adaptive load balancing agent that does not support ALB

C. The company implemented a host multipath driver that does not support ALB

D. The company implemented a host type that does not support ALB

Correct Answer: CD

Reference: https://mysupport.netapp.com/NOW/public/eseries/sam/index.html#page/GUID-8538272AB802-49D9-9EA2-96C82DAD26A2/GUID-90A829B6-ACEE-41C6-8595-91C7D90554EB.html

QUESTION 9

A customer has launched a data analytics initiative and has been transferring old data into the new data lake. The customer has discovered some data read errors during the transfer process.

![Pass2Lead](https://Pass2Lead.com)
In this scenario, how should the customer have avoided these data integrity issues?

A. by ensuring that data assurance and media scan are always activated

B. by deploying secure-capable drives

C. by turning on cyclic redundancy checks (CRCs)

D. by turning on erasure coding

Correct Answer: A

QUESTION 10

Where would you find the version of the driver and firmware for QLogic HBAs that are supported by NetApp E-Series systems?

A. Interoperability Matrix Tool

B. SANtricity Admin Guide

C. Hardware Universe

D. QLogic download webpage

Correct Answer: D

[NS0-515 PDF Dumps](#)   [NS0-515 Practice Test](#)   [NS0-515 Exam Questions](#)