

API-571^{Q&As}

Corrosion and Materials Professional

Pass API API-571 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass2lead.com/api-571.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by API Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers





https://www.pass2lead.com/api-571.html 2024 Latest pass2lead API-571 PDF and VCE dumps Download

QUESTION 1
In order to minimize and prevent amine SCC, PWHT all carbon steel welds in accordance with API RP
A. 751
B. 912
C. 510
D. 945
Correct Answer: D
QUESTION 2
and damage develop without applied or residual stress so that PWHT will not prevent them from occurring.
A. SOHIC, Blistering
B. SCC, SOHIC
C. HIC, SCC
D. Blistering, HIC
Correct Answer: D
QUESTION 3
Improved resistance to erosion is usually achieved through increasing substrate using harder alloys, hard facing or face-hardening treatment.
A. Composition
B. Stress
C. Hardness
D. None of the above
Correct Answer: C
QUESTION 4
is a form of erosion caused by the formation and instantaneous collapse of innumerable tiny vapor bubbles.
A. Condensate corrosion



https://www.pass2lead.com/api-571.html 2024 Latest pass2lead API-571 PDF and VCE dumps Download

B. Cavitation			
C. Dew-Point corrosion			
D. Atmospheric corrosion			
Correct Answer: B			
QUESTION 5			
High strength, low allow steels such as A193-B7 bolts and compressor parts are susceptible to hydrogen stress cracking. A193-B7M bolts are susceptible if			
A. Exposed			
B. Overtorqued			
C. Double nutted			
D. None of the above			
Correct Answer: B			
Latest API-571 Dumps	API-571 PDF Dumps	API-571 Practice Test	