

6002.1^{Q&As}

Avaya Aura(TM) Communication Manager and CM Messaging (R6.0)
Implementation Exam

Pass Avaya 6002.1 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass2lead.com/6002-1.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



QUESTION 1

On a media gateway G450, which slots are permitted for the MM 342?

- A. V1 and V2
- B. V6 and V6
- C. V3 and V8
- D. V5 and V7

Correct Answer: C

QUESTION 2

Which communication manager 6.0 command is used to add a new survivable

- A. add surviveable-processor
- B. add survivable-processor ess
- C. add survivable-processor core
- D. add survivable-processor

Correct Answer: D

QUESTION 3

A user at extension 1111 complains that when dialing extension 2222, the call is the call is unexpectedly answered by a person at extension 3333. All other calls made are connected as expected. There is not display on the phone. While at the SAT, the technician has the user repeat the call to extension 2222

Which command identifies the reason this phone call is behaving in the expected way?

- A. List trace station 1111
- B. List trace station 3333
- C. Status station 1111
- D. Display station 3333

Correct Answer: A

QUESTION 4

Which Avaya G450 Module provides 8 DCP ports?

- A. MM711
- B. MM712
- C. MM7202
- D. TN2224

Correct Answer: B

QUESTION 5

A customer has selected Avaya Aura CM_survremote_embedded template.

Which Avaya server should be used?

- A. S8730 Server 8Gb RAM
- B. S8800 Server
- C. S8510Server with 8GB RAM
- D. S8300D Server

Correct Answer: D

[6002.1 VCE Dumps](#)

[6002.1 Exam Questions](#)

[6002.1 Braindumps](#)