

HP2-T23^{Q&As}

Supporting Industry Standard Server Solutions

Pass HP HP2-T23 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass2lead.com/hp2-t23.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



QUESTION 1

What are features of the HP ProLiant MicroServer? (Select two.)

- A. Sound level of at least 85 DBa
- B. SATA 3.5 inch LFF drives
- C. SAS 2.5 inch SC hot-plug drives
- D. AMD processor
- E. Intel processor
- F. Fibre Channel drives

Correct Answer: BD

QUESTION 2

What should you use to update firmware on several HP VC Ethernet or Fibre Channel modules simultaneously?

- A. Onboard Administrator (OA)
- B. Virtual Connect Manager (VCM)
- C. BladeSystem Firmware Deployment Tool (FDT)
- D. Virtual Connect Support Utility (VCSU)

Correct Answer: D

QUESTION 3

If you install two Onboard Administrator modules with different firmware revisions in a c7000 enclosure, which module will be active by default?

- A. The one on the left of the enclosure
- B. The one on the right of the enclosure
- C. The one with the latest firmware, regardless of position
- D. The one with the original firmware regardless of position

Correct Answer: C

QUESTION 4

What can an engineer use to ensure quick, precise, intelligent installation when installing CPUs in a ProLiant Gen8 server?

- A. HP Intelligent Provisioning
- B. HP Smart Socket Guide
- C. HP Hot Plug CPU Sockets
- D. HP CPU Slot Isolation

Correct Answer: B

QUESTION 5

How wide must the a data center door be to allow an HP MCS G2 rack to be brought into the data center?

- A. 45 cm (1.5 feet)
- B. 60 cm (2 feet)
- C. 80 cm (2.5 feet)
- D. 110 cm (3.6 feet)

Correct Answer: D

[HP2-T23 PDF Dumps](#)

[HP2-T23 VCE Dumps](#)

[HP2-T23 Study Guide](#)