

HP2-T23^{Q&As}

Supporting Industry Standard Server Solutions

Pass HP HP2-T23 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass2lead.com/hp2-t23.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



QUESTION 1

From which location does Active Health collect data?

- A. iLO
- B. SMH
- C. Event Log
- D. IML

Correct Answer: A

QUESTION 2

A customer asks you to check on the remaining life of the solid state disk drives. Where can you access the SMARTSSD Wear Gauge?

- A. Array Configuration Utility (ACU)
- B. Option ROM Configuration for Arrays (ORCA)
- C. iLO home page
- D. Integrated Management log (IML)

Correct Answer: C

QUESTION 3

Which components are integrated into the HP Service Pack for ProLiant (SPP)? (Select three)

- A. HP Advanced Diagnostic Utility
- B. HP Smart Update Firmware DVD
- C. HP Advanced Configuration Utility
- D. HP ProLiant Support Packs
- E. HP Smart Update Manager
- F. HP ProLiant Version Control DVD 24 of 60

Correct Answer: ADE

QUESTION 4


Which Virtual Connect module enables FCoE or iSCSI connectivity for BladeSystem server blades?

- A. VC1/10Gb-F
- B. VC-FC8/24
- C. VC FlexFabric
- D. VCFlex-10

Correct Answer: C

QUESTION 5

A support engineer is installing DIMMs of different speeds and voltages in a ProLiant DL380p Gen8 Server. Which rules for DIMM installation must the engineer follow during this installation?



- A. Four quad-ranked LRDIMMs are supported across all memory channels. The server balances capacity automatically.
- B. RDIMMs operating at either 1.35V or 1.5V may be mixed in any order. The system will operate at the lower voltage.
- C. DIMMs of different speeds may be mixed in any order. The server will select the lowest common speed.
- D. UDIMMs, RDIMMs, and LRDIMMs may be mixed in the same bank in the server if only one processor is installed.

Correct Answer: BC

QUESTION 6

Which statements are correct about HP Systems Insight Manager (HP SIM) 7.0 Agentless Management? (Select two.)

- A. HP SIM communicates with the CPU and collects essential data for the operating system.
- B. Agentless Management is provided by the CPU.

- C. HP SIM communicates with the iLO Management Engine to collect hardware data.
- D. The Agentless Management Service runs on the host to provide software information directly to the iLO Management Engine.

Correct Answer: CD

QUESTION 7

What should you do if an online firmware flash of the system board fails?

- A. Retry the flash before rebooting the server.
- B. Replace the system board because the flash is corrupt.
- C. Download a new version of the ROM, reboot the server and try again.
- D. Reboot the server, remove power, and try again.

Correct Answer: C

QUESTION 8

Which HP tool can you use to deploy firmware and software updates to a ProLiant server blade?

- A. Insight Diagnostics
- B. Software Update Manager
- C. System Management Homepage
- D. Service Pack for ProLiant

Correct Answer: B

QUESTION 9

What should an administrator do to prevent discharge of static electricity when replacing components in a ProLiant server? (Select two.)

- A. Place the server blade on a flat, level surface.
- B. Wear a plastic grounding strap to remove the ESD-sensitive component from the static safe container
- C. Place the ESD-sensitive component on a grounded surface.
- D. Wear a cloth grounding strap to replace the defective component.
- E. Avoid hand contact with the ESD-sensitive component by transporting in a static-safe container.

Correct Answer: BE

QUESTION 10

Why should you use an electrostatic discharge (ESD) wrist strap when replacing parts such as memory DIMMs?

- A. A 48 V DC PSU will contribute to higher static electricity.
- B. It incorporates high resistance and dissipates electrical charges into the ozone.
- C. A current of more than 75 mA can kill someone.
- D. It prevents the part from being damaged by static electricity.

Correct Answer: D

QUESTION 11

A ProLiant DL 380 G7 server has a failure indicating that memory slot DIMM 1 has errors. To troubleshoot the problem, you exchange the memory modules in slots 1 and 2 with each other.

Now you have a memory error indicating that memory slot 1 has errors, and an amber LED next to slot 1 is lit.

What should you do?

- A. Replace the memory module in slot 1 because it is definitely bad.
- B. Replace both memory modules in slots 1 and 2.
- C. Run the ECC memory test in the diagnostics to correct the errors.
- D. Replace the system board and rerun the memory diagnostics.

Correct Answer: A

QUESTION 12

What happens if you lose or misplace a Trusted Platform Module (TPM) key?

- A. The system requests the Administrator password.
- B. The system enters diagnostic mode.
- C. The system will not boot.
- D. Data loss might occur.

Correct Answer: D

QUESTION 13

Where can you choose the server SPP for version comparison and updates?

- A. VCEM
- B. SMH
- C. VCRM
- D. VCA

Correct Answer: D

QUESTION 14

What are features of the HP ProLiant MicroServer? (Select two.)

- A. Sound level of at least 85 DBa
- B. SATA 3.5 inch LFF drives
- C. SAS 2.5 inch SC hot-plug drives
- D. AMD processor
- E. Intel processor
- F. Fibre Channel drives

Correct Answer: BD

QUESTION 15

What are features of Option ROM Configuration for Arrays (ORCA)? (Select two.)

- A. Smart Array Advanced Pack license registration
- B. Online spare assignment
- C. Drive expansion
- D. Ability to set the stripe size
- E. RAID level migration

Correct Answer: AB

[Latest HP2-T23 Dumps](#)

[HP2-T23 Study Guide](#)

[HP2-T23 Braindumps](#)